DOCKET FILE COPY ORIGINAL

BELLSOUTH

BellSouth Corporation Suite 900 1133-21st Street, N.W. Washington, D.C.20036-3351

mary.henze@bellsouth.com

April 29, 2002

Mary L. Henze
Executive Director
Federal Regulatory Affairs

202 463534109 202 463-4631 Fax

RECEIVED

Ms. Marlene H. Dortch Secretary Federal Communications Commission 445 Twelfth Street, S.W. Room TW-A325 Washington, DC 20554

APR **2** 9 2002

PROPAL COMMUNICATIONS COMMINSIONS
OFFICE OF THE SECRETARY

Re: BellSouth's Public Notices of Network Change Under Rule 51.329(a) - CC Docket No. 96-98

Dear Ms. Dortch:

BellSouth Telecommunications, Inc. ("BellSouth") hereby submits the attached original and two copies of its Public Notices of Network Change Under Rule 51.329(a) in accordance with the requirements set forth in the Commission's Second Report and Order and Memorandum Opinion and Order released August 8, 1996, in CC Docket No. 96-98. Descriptions of the changes are provided below:

Number	Type of Change Planned	Location of Change
SN91082986	Change in Outside Plant Network Facilities	Pensacola, FL
SN91082987	Change in Outside Plant Network Facilities	Pensacola, FL
SN91082988	Change in Outside Plant Network Facilities	Pensacola, FL
SN91082989	Change in Outside Plant Network Facilities	Pace, FL
SN91082990	Change in Outside Plant Network Facilities	Pensacola, FL

As required, one paper copy and one diskette copy is being submitted to the Chief of the Common Carrier Bureau's Network Services Division. Copies of the above referenced notices are also available at: http://www.interconnrction.beIlsoutli.coni/notiftcations/network/index.httnI

Should you have any questions regarding this submission, please contact me at (202) 463-4109.

2. Herr

Sincerely,

Mary L. Henze.

Executive Director - Federal Regulatory

Attachments

cc: Michelle Carey (with diskette)

Carmell Weathers (with diskette)

Carrier

BellSouth Telecommunications, Inc. 675 West Peachtree Street NE Atlanta, Georgia 30375

Date Changes are to Occur: November 1, 2002

Location of Changes: Pensacola, Florida - Along Bayou Blvd from 12th Avenue to Ironwood Road

Description **of** Change Planned: Copper feeder facilities are being replaced with fiber and Digital Loop Carrier (DLC) due to the Florida Department of Transportation road work project at I-110 and Fairfield Drive.

Description **of** Reasonably Foreseeable Impact **of** the Planned Change: After this work is completed, metallic facilities from the Belmont Central office to the affected area will no longer be available. Unbundled loops that are defined as compatible with DLC, e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system.

It should be noted that, if a competitive carrier is providing DSL via a POTS-grade unbundled loop, BellSouth has no knowledge of the presence of DSL. The POTS-grade loop is considered to be compatible with DLC. In such a case, BellSouth has no basis to notify the carrier and there will be no means to continue the service.

Contact: Technical questions Brad Huggins, Loop Capacity Manager

relating to this change 605 W Garden St

should be directed to: Pensacola, Florida 32501

(850) 436-1671

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or

780-2171 (FL, GA, NC, SC)

(If you are calling from a mandatory IO-digit calling area,

include your local area code.)

Outside BellSouth region: 1-800-786-7619 Fax: 1-205-321-2191

Carrier

BellSouth Telecommunications, Inc 675 West Peachtree Street NE Atlanta, Georgia 30375

Date Changes are to Occur: November 1,2002

Location of Changes: Pensacola, Florida - Along Bayou Blvd from 12th Avenue to Ironwood Road

Description **of** Change Planned: Copper feeder facilities are being replaced with fiber and Digital Loop Carrier (DLC) due to the Florida Department of Transportation road work project at I-110 and Fairfield Drive.

Description **of** Reasonably Foreseeable Impact of the Planned Change: After this work is completed, metallic facilities from the Belmont Central office to the affected area will no longer be available. Unbundled loops that are defined as compatible with DLC, e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system.

It should be noted that, if a competitive carrier is providing DSL via a POTS-grade unbundled loop, BellSouth has no knowledge of the presence of DSL. The POTS-grade loop is considered to be compatible with DLC. In such a case, BellSouth has no basis to notify the carrier and there will be no means to continue the service.

Contact: <u>Technical questions</u> Brad Huggins, Loop Capacity Manager

relating to this change 605 W Garden St

should be directed to: Pensacola, Florida 32501

(850) 436-1671

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or

780-2171 (FL. GA, NC, SC)

(If you are calling from a mandatory IO-digit calling area,

include your local area code.)

Outside BellSouth region: 1-800-786-7619 Fax: 1-205-321-2191

Notice of Network Change Under Rule 51.329(a) Notification No. SN91082987 Issue Date: April 29,2002

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: November 1, 2002

Location of Changes: Pensacola, Florida - Along Bayou Blvd from 12th Avenue to Ironwood Road

Description of Change Planned: Copper feeder facilities are being replaced with fiber and Digital Loop Carrier (DLC) due to the Florida Department of Transportation road work project at I-110 and Fairfield Drive.

Description of Reasonably Foreseeable Impact of the Planned Change: After this work is completed, metallic facilities from the Belmont Central office to the affected area will no longer be available. Unbundled loops that are defined as compatible with DLC, e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system.

It should be noted that, if a competitive carrier is providing DSL via a POTS-grade unbundled loop, BellSouth has no knowledge of the presence of DSL. The POTS-grade loop is considered to be compatible with DLC. In such a case, BellSouth has no basis to notify the carrier and there will be no means to continue the service.

Contact: Technical questions Brad Huggins, Loop Capacity Manager

relating to this change 605 W Garden St

should be directed to: Pensacola, Florida 32501

(850) 436-1671

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or

780-2171 (FL, GA, NC, SC)

(If you are calling from a mandatory IO-digit calling area,

include your local area code.)

Outside BellSouth region: 1-800-786-7619 Fax: 1-205-321-2191

Notification No. 3 7 Issue Date: April 29,2002

Carrier

BellSouth Telecommunications, Inc. 675 West Peachtree Street NE Atlanta, Georgia 30375

Date Changes are to Occur: November 1, 2002

Location of Changes: Pensacola, Florida - Along Bayou Blvd from 12th Avenue to Ironwood Road

Description **d** Change Planned: Copper feeder facilities are being replaced with fiber and Digital Loop Carrier (DLC) due to the Florida Department of Transportation road work project at 1-110 and Fairfield Drive.

Description **of** Reasonably Foreseeable Impact **of** the Planned Change: After this work is completed, metallic facilities from the Belmont Central office to the affected area will no longer be available. Unbundled loops that are defined as compatible with DLC, e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system.

It should be noted that, if a competitive carrier is providing DSL via a POTS-grade unbundled loop, BellSouth has no knowledge of the presence of DSL. The POTS-grade loop is considered to be compatible with DLC. In such a case, BellSouth has no basis to notify the carrier and there will be no means to continue the service.

Contact: Technical questions Brad Huggins, Loop Capacity Manager

relating to this change 605 W Garden St

should be directed to: Pensacola, Florida 32501

(850) 436-1671

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, **KY**, LA, MS, TN) or

780-2171 (FL, GA, NC, SC)

(If you are calling from a mandatory IO-digit calling area,

include your local area code.)

Outside BellSouth region: 1-800-786-7619 Fax: 1-205-321-2191

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: November 1,2002

Location of Changes: Pensacola, Florida - Along Bayou Blvd from 12th Avenue to Ironwood Road

Description of Change Planned: Copper feeder facilities are being replaced with fiber and Digital Loop Carrier (DLC) due to the Florida Department of Transportation road work project at l-110 and Fairfield Drive.

Description of Reasonably Foreseeable Impact of the Planned Change: After this work is completed, metallic facilities from the Belmont Central office to the affected area will no longer be available. Unbundled loops that are defined as compatible with DLC, e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system.

It should be noted that, if a competitive carrier is providing DSL via a POTS-grade unbundled loop, BellSouth has no knowledge of the presence of DSL. The POTS-grade loop is considered to be compatible with DLC. In such a case, BellSouth has no basis to notify the carrier and there will be no means to continue the service.

Contact: Technical questions Brad Huggins, Loop Capacity Manager

relating to this change 605 W Garden St

should be directed to: Pensacola, Florida 32501

(850) 436-1671

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or

780-2171 (FL, GA, NC, SC)

(If you are calling from a mandatory IO-digit calling area,

include your local area code.)

Outside BellSouth region: 1-800-786-7619 Fax: 1-205-321-2191

Carrier

BellSouth Telecommunications, Inc. 675 West Peachtree Street NE Atlanta, Georgia 30375

Date Changes are to Occur: November 1, 2002

Location of Changes: Pensacola, Florida - Along Bayou Blvd from 12th Avenue to Ironwood Road

Description **of** Change Planned: Copper feeder facilities are being replaced with fiber and Digital Loop Carrier (DLC) due to the Florida Department of Transportation road work project at I-110 and Faitfield Drive.

Description **of** Reasonably Foreseeable Impact **of** the Planned Change: After this work is completed, metallic facilities from the Belmont Central office to the affected area will no longer be available. Unbundled loops that are defined as compatible with DLC, e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system.

It should be noted that, if a competitive carrier is providing DSL via **a** POTS-grade unbundled loop, BellSouth has no knowledge of the presence of DSL. The POTS-grade loop is considered to be compatible with DLC. In such a case, BellSouth has no basis to notify the carrier and there will be no means to continue the service.

Contact: <u>Technical questions</u> Brad Huggins, Loop Capacity Manager

relating to this change 605 W Garden St

should be directed to: Pensacola, Florida 32501

(850) 436-1671

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, **MS,** TN) or

780-2171 (FL, **GA**, NC, SC)

(If you are calling from a mandatory IO-digit calling area,

include your local area code.)

Outside BellSouth region: 1-800-786-7619 Fax: 1-205-321-2191

Notice of Network Change Under Rule 51.329(a) Notification No. SN91082987 issue Date: April 29,2002